

Date: Wednesday, 07/05/2008 1:10:08 PM
 User: Julie Lecocq

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.	Drawing Name	: D3552-11
Job Number	: 39107		
Estimate Number	: 10804		
P.O. Number	:	Part Number	: D355211
This Issue	: 07/05/2008	S.O. No.	:
Prsht Rev.	: NC	Drawing Number	: R08-045/NCR08-037
First Issue	: 07/05/2008	Project Number	:
Previous Run	: 00015	Drawing Revision	:
	Type : PURCHASED PARTS	Material	:
Written By	:	Due Date	: 14/05/2008
Checked & Approved By	: <u>JULIE LECOQ</u>	Qty:	1 Um: Each
Comment	:		

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
----------------	------------------------------	----------------------

1.0	D355211	Gas Spring
-----	---------	------------



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)
 Gas Spring
 original B33533

2.0	QC5	INSPECT WORK TO CURRENT STEP
-----	-----	------------------------------



Comment: INSPECT WORK TO CURRENT STEP
 Scrap and destroy strut. See NCR08-037 for more details.

3.0	QC21	FINAL INSPECTION/W/O RELEASE
-----	------	------------------------------



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



mf 08-06-16

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries